

DESCRIPTION

OmegaTopCoat is a premium quality, single-pack, solvent-based floor paint with an attractive mid sheen finish suitable for concrete wood and steel with outstanding durability for exterior and interior application.

Due to excellent film hardness and erosion resistance, OmegaTopCoat is capable of standing up to scuffing in light to medium traffic areas, mild chemical spillage and repeated washing. Under normal circumstances, this ensures your environment achieves a lasting, high-quality look.

KEY BENEFITS

- Tough & Durable Smooth Floor Finish
- For Light to Medium Traffic Areas
- Outdoor Applications, UV Resistant & Non-Yellowing
- Fast Drying Properties.& Can be Solved by White Spirit
- Easy to Apply
- Mid-Sheen Finish

PRODUCT APPLICATION

RECOMMENDED COATING LAYERS

STEPS	PRODUCT
On Concrete:	
1st Coat as a Primer	OmegaEpoxyPrimer No.11002 (Diluted 30%)
2 to 3 Coats	OmegaTopCoat No.190
On Metal:	
1st Coat as a Primer	OmegaEpoxyZincRichPrimer No.11088
2 Coats	OmegaTopCoat No.190

APPLICATION METHOD

OmegaTopCoat can be applied by brush, roller or airless spray. As with other solvent-based paints, do not apply in temperatures below 5°C.

THINNING

OmegaTopCoat should be mixed before use, and can be diluted with Omega-Sol-180 or White Spirit from 15-20% for the first coat and 10-15% for the second coat.

SURFACE PREPARATION

Surfaces to be coated must be fully dry, clean, sound, and free from all contamination including loose and peeling paint, dirt, grease, oil, wax, concrete curing agents and bond breakers, chalk, efflorescence, mildew, rust, product fines, and dust. Remove loose paint, chalk, and efflorescence by wire brushing, scraping, or sanding.

PRACTICAL COVERAGE

On smooth surfaces of average porosity, a guide to the practical coverage that can be achieved in 1 coat is up to 18m² per U.S. Gallon.

DRYING TIMES

Single coat at standard thickness:

- Touch Dry: 4-6 hours.
- Recoat: 16-24 hours.

NOTE:

It is essential to allow the coated floor to dry for a minimum of 24 hours under well ventilated conditions before light use and 72 hours for heavy use.

CLEAN UP

When finished, wash tools and equipment with White Spirit. Properly dispose of all soiled rags and store unused product at room temperature.